


Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hrs.	Min.	Hrs.	Min.	
Brought Forward	→				

N157CD 9-25-19 Hobbs 2092 FLT 100 hr inspection completed this date i/a/w Continental Maintenance Manual. Spark plugs cleaned, tested and re-installed. Compression checked #1-74, 2-75, 3-75, 4-76, 5-76, 6-75/80. Timing checked, exhaust inspected. Oil filter replaced with AA48108 and old filter inspected and found ok. Fuel nozzles cleaned. Air filter replaced with BA-24. Changed Oil with Aeroshell W100 plus. A/C belt insp and re-tensioned. All lines and fitting inspected. A.D. notes reviewed through biweekly supplemental Tdata 2019-18. I certify that this engine has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

Total time: 2092 SMOH 692
 Inspection Authorization #3257972



Hevle Aircraft Inc
 PO Box 21884
 Burbank, CA 91508
 Aircraft maintenance and Repair
 818 425-9147