


YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				

N157CD 9-25-19 Hobbs 2092 FLT 100 hr. inspection completed this date i/a/w Cirrus SR20 Maintenance Manual. All pulleys and cables inspected. Gill battery checked, performed capacity test and passed at 85%, next due at 400 +/- 25hrs or 6 months per Gill ICA. ELT system check i/a/w FAR 91.207(d)1-4 ELT battery due 03/2027. Fuel injection screen insp and cleaned. All rod end bearings bushings and bell cranks inspected and lubed. Main and nose wheel bearings inspected and repacked, brakes inspected. Brake fluid serviced. Air filter Replaced with BA-24. All A.D. notes reviewed through biweekly supplemental Tdata 2019-18. **I certify that this Aircraft has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.**

Total time: 2092

 Inspection Authorization #3257972



Hevle Aircraft Inc
 PO Box 21854
 Bakersfield CA 93390
 Aircraft maintenance and Repair
 661-419-9167
